

PressurePro Active Cleaner, alkaline RM 81 eco!efficiency

Universal high-pressure cleaning concentrate for removing stubborn oil, grease and mineral contamination. With the ecolefficiency formulation, it is especially economical, effective and environmentally friendly.

pH 12.3 in concentrate











Properties

- Effective, ecological, high-pressure detergent
- Loosens heavy oil, grease and mineral-based soiling
- Cleaning action in all temperature ranges
- Gentle and ecofriendly
- Pleasant, fresh fragrance
- Tensides biodegradable in accordance with EEC 648/2004
- Quick oil and water separation in the oil separator (easily separable = asf)
- NTA free
- Phosphate-free
- Silicone-free

Application

- High-pressure washers
- Spray units

Areas		
Agriculture	Transport and machines	
Car dealership and garage	Car/engine wash, Parts cleaning	
Building Industry	Transport and machines	
Industry	Surface degreasing	
Municipal	Car/engine wash	
Haulage contractors, bus operators	Tarpaulin cleaning, Car/engine wash	
Food and drink industry	Floor and surface cleaning	



Application

High-pressure washers

- Apply primary mixture with fresh water.
- Set the dosage and temperature on the device. (Possible use of the ecolefficiency mode (60°C))
- Clean object, working in overlapping sections.
- Rinse surface well with clear water.
- In food-processing applications, rinse thoroughly with drinking water.

Spray attachment

- Combine the product with the appropriate dosage and fresh water.
- Wet object completely with the product.
- Allow to soak.
- Contact time 1-5 minutes, depending on the degree of soiling.
- Rinse surface well with clear water.
- In food-processing applications, rinse thoroughly with drinking water.



Directions for use

- In the food sector, rinse thoroughly with drinking water.
- Test on an inconspicuous part for material compatibility.
- Do not let the cleaning solution dry out.
- Store away from frost.

Warnings and safety recommendations according to EC Directives

- Danger
- H314 Causes severe skin burns and eye damage
- H290 May be corrosive to metals
- P280 Wear protective gloves/protective clothing/eye protection/face protection.
- P303 + P361 + P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower].
- P305 + P351 + P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
- P310 Immediately call a POISON CENTER/doctor.
- P405 Store locked up.
- P501a Dispose of contents/container in accordance with local/regional/national/international regulations.

Further information

■ Material Safety Data Sheet (MSDS)

Dosage and yield						
Content	Cleaning method	Primary mixture	Dosage	Contamination	Productivity	
1000 ml	High-pressure cleaner (80 °C)	1+3	0.75 - 4 %	medium	260 m²	
1000 ml	High-pressure cleaner (60 °C)	1+3	1 - 5 %	medium	260 m²	
1000 ml	Spray units		5 - 25 %	heavy	220 m²	